



BRUHATH BENGALURU MAHANAGARA PALIKE

**Horamavu/Kalkere Main Road, Jayanthi Nagara Circle, Horamavu Village,
Bangalore – 560113.**

No.AEE/HRM/PR/386/2025-26

Date: 23/04/26

Office of the Assistant Executive Engineer
B.B.M.P Horamavu Sub-Division
Mahadevapura Zone
Bangalore, Karnataka

Sub:- Regarding issue of School building safety certificate.

Ref :- Your Request letter Dated: 01.04.2025

With reference to the above subject, we here by certify Samsidh international School, No. 582/2, 583/2, Kalkere Village, K.R.Puram Hobli, Horamavu Bangalore – 113. Ramamurthy Nagara Ward No.26, Has been inspected on Date:23.04.2025 The building is comprises R.C.C Framed structure of Ground Floor, First Floor, Second Floor & Third Floor the building has been constructed in the year 2015-16. In the Building General safety, Light, Air and Ventilation are seems to be adequate.

The Structural safety Should be got certified from the Private Structural Experts. Since the structural Analysis Department is not exists in the Bruhath Bengaluru Mahanagara Palike.

Yours faithfully,

Assistant Executive Engineer
Horamavu Sub-Division
BBMP

To,
M//Vasa Shrinivas Rao.
Samsidh international School,
No. 582/2, 583/2, Kalkere Village,
K.R.Puram Hobli, Horamavu
Bangalore – 113.